



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>DE/EPS/QAR17.0003/58</b>	Page 1 of 3
QAR Free Ref. No.:	<b>23TH0040_A1, 23TH0036_A1, 23TH0034_A1, 23TH0037_A1, 23TH0039_A1, 23TH0041_A1, 23TH0033_A1, 23TH0038_E</b>	Status: <b>Issued</b> Date of issue: <b>2023-06-30</b>
Details of change:	<ul style="list-style-type: none"><li>- Renewal audit completed Phoenix Mecano Saudi Arabia LLC (Audit date: 2023-05-16)</li><li>- Renewal audit completed Phoenix Mecano S.E. Asia Pte. Ltd., Singapore (Audit date: 2023-03-27)</li><li>- Renewal audit completed PHOENIX MECANO (INDIA) PRIVATE LIMITED., India (Audit date: 2023-03-23)</li></ul>	Valid until: <b>2026-02-27</b> Audit date: <b>2023-05-16</b>
Location(s) audited:	<p><b>Phoenix Mecano Kecskemét</b> Szent István krt. 24 Kecskemét 6000 <b>Hungary</b></p> <p><b>ROSE Systemtechnik GmbH + Co. KG</b> Erbeweg 13 - 15 32457 Porta Westfalica <b>Germany</b></p> <p><b>Phoenix Mecano B.V.</b> Havenstraat 100 7005 AG Doetinchem <b>Netherlands</b></p> <p><b>Phoenix Mecano Saudi Arabia LLC</b> Building no 3267 King Abdul Aziz Road Unit No 1 Dharan Dammam 3451 <b>Saudi Arabia</b></p> <p><b>Phoenix Mecano S.E. Asia Pte. Ltd.</b> 53 Ubi Ave 3#04-01 Colourscan Building Singapore 408863 <b>Singapore</b></p> <p><b>PHOENIX MECANO (INDIA) PRIVATE LIMITED</b> Pirangut Industrial Area, Post Ghotawade Plot 388, Village Bhare, Taluka Mulshi Pune 412115 <b>India</b></p> <p><b>Phoenix Mecano India Pvt. Ltd</b> Plant III, Gat No 408, 410 &amp; 412 Village - Urse, Taluka-Maval Talegaon Urse, Road Pune 410506 <b>India</b></p> <p><b>Phoenix Mecano Inc.</b> 7330 Executive Way Frederick MD 21704 <b>United States of America</b></p> <p><b>Rose Systemtechnik Middle East</b> B.o. Box 8993</p>	



# IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/EPS/QAR17.0003/58**

Page 2 of 3

Sharjah  
**United Arab Emirates**

**Mecano Components Co., Ltd/012**  
No. 1001, Jiaqian Road, Nanxiang, Jiading District  
Shanghai P.R.C. 201802  
**China**

**Phoenix Mecano nv**  
Karrewegstraat 124  
Deinze 9800  
**Belgium**

Issuing ExCB: **EPS - Bureau Veritas Consumer Products Services Germany GmbH**

Manufacturer: **Rose Systemtechnik GmbH**  
Erbeweg 13-15  
32457 Porta Westfalica  
Germany

Location of  
Manufacturer: **Germany**

Product information: Production, final inspection and testing of  
Junction boxes, empty enclosures, control enclosures fitted with terminal blocks, fieldbus, devices, remote I/O and  
switches, cable glands and installation fittings

Type of protection: **i, d, e, t, op is, m, n, op pr**

Related QARs:

<a href="#">DE/EPS/QAR17.0003/00</a>	<a href="#">DE/EPS/QAR17.0003/01</a>	<a href="#">DE/EPS/QAR17.0003/02</a>
<a href="#">DE/EPS/QAR17.0003/03</a>	<a href="#">DE/EPS/QAR17.0003/04</a>	<a href="#">DE/EPS/QAR17.0003/05</a>
<a href="#">DE/EPS/QAR17.0003/06</a>	<a href="#">DE/EPS/QAR17.0003/07</a>	<a href="#">DE/EPS/QAR17.0003/08</a>
<a href="#">DE/EPS/QAR17.0003/09</a>	<a href="#">DE/EPS/QAR17.0003/10</a>	<a href="#">DE/EPS/QAR17.0003/11</a>
<a href="#">DE/EPS/QAR17.0003/12</a>	<a href="#">DE/EPS/QAR17.0003/13</a>	<a href="#">DE/EPS/QAR17.0003/14</a>
<a href="#">DE/EPS/QAR17.0003/15</a>	<a href="#">DE/EPS/QAR17.0003/16</a>	<a href="#">DE/EPS/QAR17.0003/17</a>
<a href="#">DE/EPS/QAR17.0003/18</a>	<a href="#">DE/EPS/QAR17.0003/19</a>	<a href="#">DE/EPS/QAR17.0003/20</a>
<a href="#">DE/EPS/QAR17.0003/21</a>	<a href="#">DE/EPS/QAR17.0003/22</a>	<a href="#">DE/EPS/QAR17.0003/23</a>
<a href="#">DE/EPS/QAR17.0003/24</a>	<a href="#">DE/EPS/QAR17.0003/25</a>	<a href="#">DE/EPS/QAR17.0003/26</a>
<a href="#">DE/EPS/QAR17.0003/27</a>	<a href="#">DE/EPS/QAR17.0003/28</a>	<a href="#">DE/EPS/QAR17.0003/29</a>
<a href="#">DE/EPS/QAR17.0003/30</a>	<a href="#">DE/EPS/QAR17.0003/31</a>	<a href="#">DE/EPS/QAR17.0003/32</a>
<a href="#">DE/EPS/QAR17.0003/33</a>	<a href="#">DE/EPS/QAR17.0003/34</a>	<a href="#">DE/EPS/QAR17.0003/35</a>
<a href="#">DE/EPS/QAR17.0003/36</a>	<a href="#">DE/EPS/QAR17.0003/37</a>	<a href="#">DE/EPS/QAR17.0003/38</a>
<a href="#">DE/EPS/QAR17.0003/39</a>	<a href="#">DE/EPS/QAR17.0003/40</a>	<a href="#">DE/EPS/QAR17.0003/41</a>
<a href="#">DE/EPS/QAR17.0003/42</a>	<a href="#">DE/EPS/QAR17.0003/43</a>	<a href="#">DE/EPS/QAR17.0003/44</a>
<a href="#">DE/EPS/QAR17.0003/45</a>	<a href="#">DE/EPS/QAR17.0003/46</a>	<a href="#">DE/EPS/QAR17.0003/47</a>
<a href="#">DE/EPS/QAR17.0003/48</a>	<a href="#">DE/EPS/QAR17.0003/49</a>	<a href="#">DE/EPS/QAR17.0003/50</a>
<a href="#">DE/EPS/QAR17.0003/51</a>	<a href="#">DE/EPS/QAR17.0003/52</a>	<a href="#">DE/EPS/QAR17.0003/53</a>
<a href="#">DE/EPS/QAR17.0003/54</a>	<a href="#">DE/EPS/QAR17.0003/55</a>	<a href="#">DE/EPS/QAR17.0003/56</a>
<a href="#">DE/EPS/QAR17.0003/57</a>		

Related Certificates (manual insertion)::

**IECEX PTB 08.0003U**  
**IECEX PTB 08.0005U**

Related Certificates (automatic linking)::



# IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/EPS/QAR17.0003/58**

Page 3 of 3

Related Certificates for  
previous versions:

IECEX CES 18.0007X issue: 0  
IECEX DEK 18.0069U issue: 0  
IECEX DEK 18.0073X issue: 0  
IECEX DEK 18.0076X issue: 0  
IECEX IMQ 18.0006X issue: 1  
IECEX ITS 15.0041X issue: 3  
IECEX ITS 21.0014U issue: 0  
IECEX ITS 22.0011U issue: 0  
IECEX PTB 07.0059U issue: 4  
IECEX PTB 07.0060X issue: 5  
IECEX PTB 08.0006X issue: 2  
IECEX PTB 14.0036 issue: 2  
IECEX PTB 20.0008U issue: 0

IECEX CES 19.0019X issue: 0  
IECEX DEK 18.0070U issue: 0  
IECEX DEK 18.0074X issue: 0  
IECEX IMQ 18.0005X issue: 0  
IECEX INE 22.0041X issue: 0  
IECEX ITS 15.0043X issue: 2  
IECEX ITS 21.0031U issue: 0  
IECEX ITS 22.0015X issue: 0  
IECEX PTB 07.0059U issue: 5  
IECEX PTB 07.0060X issue: 6  
IECEX PTB 14.0036 issue: 0  
IECEX PTB 14.0037 issue: 0  
IECEX PTB 20.0008U issue: 1

IECEX DEK 18.0068U issue: 0  
IECEX DEK 18.0071U issue: 0  
IECEX DEK 18.0075X issue: 0  
IECEX IMQ 18.0006X issue: 0  
IECEX INE 22.0041X issue: 1  
IECEX ITS 16.0002U issue: 1  
IECEX ITS 22.0001X issue: 0  
IECEX ITS 22.0015X issue: 1  
IECEX PTB 07.0060 issue: 4  
IECEX PTB 08.0004 issue: 5  
IECEX PTB 14.0036 issue: 1  
IECEX PTB 14.0038X issue: 0  
IECEX PTB 20.0008U issue: 2

Comments: